Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 6/10/2014, 6/11/2014, 6/12/2014	Man Days: 3
Inspection Unit: Marion	
Location of Audit: Marion	
Exit Meeting Contact: Dallas Jett	
Inspection Type: Standard Inspection - Record Audit	
Pipeline Safety Representative(s): Valerie Schwing	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Dallas Jett	Sr. Quality Assurance Consultant	

Gas System Operations	Status
Gas Transporter	Ameren Illinois
Annual Report (Form 7100.1-1) reviewed for the year:	2013
Unaccounted for Gas	0.32%
Number of Services	824016
Miles of Main	16941
Is the operator maintaining documentation verifying their Maximum Allowable Operating Pressure(s)? (MAOP)	Satisfactory
Operating Pressure (Feeder)	Various
Operating Pressure (Town)	Various
Operating Pressure (Other)	Various

MAOP (Feeder)		Various
MAOP (Town)		Various
MAOP (Other)		Various
Does the operator have any transmission pipe	elines?	Yes
Regulate	ory Reporting Records	Status
Category Comment:  The regulatory reporting records are kept at the Pawnee	location.	
[191.5]	Were Telephonic Notices of Incidents reported to the NRC (800-424-8802)?	Not Checked
[191.9(a)]	Was a DOT Incident Report Form F7100.1 submitted within 30 days after detection of an incident?	Not Checked
[191.9(b)]	Were any supplemental incident reports submitted when deemed necessary?	Not Checked
Did the operator have any plastic pipe failures	s in the past calendar year?	Not Checked
Did the operator take action to mitigate safety components?	concerns relating to the failure of the PE or pipeline	Not Checked
[191.23(a)]	Did the operator report Safety Related Conditions?	Not Checked
[191.25]	Did the Operator file a Safety Related Condition Report within 5 working days of determination, but not later than 10 working days after discovery?	Not Checked
[192.16(c)]	Customer Notification: Has the operator notified each new customer within 90 days about the customer's responsibility regarding buried piping, however, operators of a master meter may continuously post a general notice in a permanent location?	Not Checked
[	DRUG TESTING	Status
Refer to Drug and Alcohol Inspection Forms a	and Protocols	Not Checked
General Comment:		
The records for the Drug and Alcohol Plan are kept in St.	Louis.	
TEST REQUIREMENTS		Status
Category Comment:		
Staff reviewed the pressure test documentation for the ca	alendar year 2012 and 2013.	
[192.517(a)][192.505,192.507,192.511(c)]	Are pressure test records being maintained for piping operating above 100 psig?	Satisfactory
[192.517(b)][192.511,192.509,192.513]	Are pressure test records being maintained for at least 5 years on piping operating below 100 psig?	Satisfactory

[192.603(b)][192.725]	Were service lines temporarily disconnected from the main properly tested prior to reconnection?	Satisfactory
	UPRATING	Status
Category Comment:		
Ameren has not done any uprating for the Mari	on or Carbondale areas in 2012 or 2013.	
[192.555][192.555]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of 30% or more SMYS?	Not Applicable
[192.557][192.557]	Has the operator maintained documentation of uprating activities when uprating a pipe to a pressure that will produce a hoop stress of less than 30% SMYS?	Not Applicable
	OPERATIONS	Status
Category Comment:		
The operation records are kept at the Pawnee	location.	
[192.603(b)][192.605(a)]	Has the operator conducted a review of the Operations and Maintenance Manual once per yr/15 months?	Not Checked
Has the operator conducted a review of the Operator Qualification Plan once per yr/15 months?		Not Checked
[192.603(b)][192.605(b)(3)]	Are construction records, maps, and operating history available to operating personnel?	Not Checked
[192.603(b)][192.605(b)(8)]	Has the operator periodically reviewed personnel's work to determine the effectiveness of normal O&M procedures when deficiencies are found?	Unsatisfactory
Issue Comment:		
	ois Gas Leak Case Field Reports. During this review Staff noted that many of the sketches of detail. In order for this issue to be closed the Marion and Carbondale areas must have a tra ts.	
CONTIN	IUING SURVEILLANCE RECORDS	Status
Category Comment:		
The continuing surveillance records are kept at	the Pawnee location.	
[192.603(b)][192.613(a)]	Has the operator reviewed continuing surveillance records for class location changes, failures, leak history, corrosion, changes in cathodic protection, and other unusual operating and maintenance conditions?	Not Checked
[192.491][192.489]	Does the operator have records verifying if exposed cast iron was examined for evidence of graphitization and if necessary what appropriate action was taken concerning graphitization?	Not Applicable
General Comment:		

Ameren has no known cast iron in the system.		
[192.603(b)][192.755]	Does the operator have surveillance records of cast iron pipelines, including appropriate action resulting from tracking circumferential cracking failures, study of leak history, or any other unusual operating and maintenance conditions?	Not Applicable
General Comment:	·	
Ameren has no known cast iron in the system.		
[192.603(b)][192.753(a)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of more than 25 (psig.) sealed as required?	Not Applicable
General Comment:		
Ameren has no known cast iron in the system.		
[192.603(b)][192.753(b)]	Is each cast iron caulked bell and spigot joint that is subject to a pressure of 25 (psig.) or less and is exposed for any reason sealed as required?	Not Applicable
General Comment:	<u> </u>	
Ameren has no known cast iron in the system.		
QUALIFIC	ATION OF PIPELINE PERSONNEL	Status
Refer to operator Qualification Inspection	on Forms and Protocols	Not Checked
General Comment:		
The OQ records are kept at the Pawnee location.		
DAMA	AGE PREVENTION RECORDS	Status
Category Comment:		
The damage prevention records are kept at the F	Pawnee location.	
[192.603(b)][191.11(a)]	Did the operator track the number of damages per 1000 locate requests for the previous years?	Not Checked
Has the number of damages increased	or decreased from prior year?	Not Checked
[192.603(b)][192.617]	Does the operator track records of accidents due to excavation damage to ensure causes of failures are addressed to minimize the recurrence?	Not Checked
[192.603(b)][192.614(c)(3)]	Does the operator provide documentation pertaining to notification of excavation, marking, positive response, and the availability and use of the one call system?	Not Checked
Does the operator have a Quality Assurfacilities?	rance Program in place for monitoring the locating and marking of	Not Checked

Do pipeline operators include performance measures in facility locating contracts?		Not Checked
[IL ADM. CO.265.100(b)(1)]	Was third party damage to mains involving a release of gas reported to ICC JULIE Enforcement? http://www.icc.illinois.gov/julie/	Not Checked
Has the Operator adopted applicable se	ection of the Common Ground Alliance Best Practices?	Not Checked
If no, were Common Ground Alliance B	est Practices discussed with Operator?	Not Checked
	EMERGENCY PLANS	Status
Category Comment:		
The emergency plan records are kept at the Paw.	nee location.	
[192.603(b)][192.615(b)(1)]	Are supervisors, responsible for emergency action, furnished copies of the latest edition of the Emergency Plan?	Not Checked
[192.603(b)][192.615(b)(2)]	Has the operator maintained documentation that the appropriate operating personnel have received training to assure they are knowledgeable of emergency procedures and that the training was effective?	Not Checked
[192.603(b)][192.615(b)(3)]	Has the operator maintained documentation of employee activity reviews to determine whether the procedures were effectively followed in each emergency?	Not Checked
[192.603(b)][192.615(c)]	Has the operator maintained documentation that the operator established and maintained liaison with appropriate fire, police and other public officials?	Not Checked
[192.603(b)][192.615(a)(3)]	Did the review of emergency response time intervals regarding odor/leak complaint documentation indicate adequate emergency response intervals were achieved?	Not Checked
PUBLIC AWARENESS PROGRAM - RECORDS		Status
Category Comment:		
The public awareness records are kept at the Pa	wnee location.	
Refer to Public Awareness Program Ins	pection Forms and Protocols	Not Checked
ODORIZATION OF GAS		Status
Category Comment:		
Staff reviewed the sniff test documentation for 20	12 and 2013. Staff also reviewed the tank level monthly inspections on the Ameren's Gas	s Compliance database.
[192.603(b)][192.625(f)]	Has the operator maintained documentation of odorant concentration level testing using an instrument?	Satisfactory
[192.603(b)][192.625(e)]	Has the operator maintained documentation of odorizer tank levels?	Satisfactory

[192.723(b)(1),192.723(b)(2)][220 ILCS 2.2.03]	After the determination of the cathodic protection	Satisfactory
[192.463,220 ILCS 2.2.03][220 ILCS 2.2.03]	Has the operator determined if cathodic protection is required on these services?	Satisfactory
[220 ILCS 2.2.03]	Has the operator designated and documented the location of all services where the meter is located more than 3 feet away from the wall of a residence?	Satisfactory
Staff reviewed the yard line surveys that were due and were	conducted in 2013. There were not any yard line surveys done in 2012.	
Category Comment:		
YARD LIN	ES - RESIDENTIAL	Status
Staff reviewed randomly selected leakage surveys for 2012 a	nd 2013, The Marion and Carbondale areas do not contain unprotected pipel	lines.
General Comment:		
[192.603(b)][192.723(b)(2)]	Is the operator performing leakage surveys outside a business district at a minimum of every 5 years/63 months? Is the operator performing leakage surveys on cathodically unprotected pipelines at a minimum of every 3 years/39 months? If the operator has inside meter sets that meet this criterion then were those surveyed? If the operator has yard lines then are those being surveyed?	Satisfactory
Staff reviewed the operator's business district surveys for 20		
General Comment:		
[192.603(b)][192.723(b)(1)]	Is the operator performing leakage surveys in business districts at a minimum of 1 per year/ 15 months? If the operator has inside meter sets that meet this criterion then were those surveyed?	Satisfactory
Staff reviewed distribution critical area patrols for 2012 and 2	013.	
General Comment:	<u> </u>	
[192.603(b)][192.721(b)(2)]	Is the operator patrolling outside business districts at a minimum of 2 per year/7 1/2 months?	Satisfactory
Staff reviewed distribution critical area patrols for 2012 and 2	013.	
General Comment:		
[192.603(b)][192.721(b)(1)]	Is the operator patrolling business districts at a minimum of 4 per year/4 1/2 months?	Satisfactory
PATROLLING	& LEAKAGE SURVEY	Status
[192.603(b)][192.625(f)(2)]	Has the master meter operator maintained documentation of sniff tests performed as required by this section?	Satisfactory
[192.603(b)][192.625(f)(1)]	Are master meter operators receiving written verification of odorant concentration levels from their gas supplier?	Satisfactory

	requirements, has the operator surveyed each line within the required leakage survey intervals?	
ABANDONMENT or D	EACTIVATION of FACILITIES PROCEDURES	Status
Category Comment:		
Staff reviewed randomly chosen work orders for 2	012 and 2013.	
[192.603(b)][192.727(b)]	Did the operator maintain documentation demonstrating that each pipeline abandoned in place was disconnected from all sources and supplies of gas, and purged of gas?	Satisfactory
[192.603(b)][192.727(c)]	Did the operator maintain documentation demonstrating that each inactive pipeline that is not being maintained under this part was disconnected from all sources and supplies of gas; purged of gas?	Satisfactory
[192.603(b)][192.727(d)]	Did the operator maintain documentation demonstrating that whenever service to a customer was discontinued access to gas was either; locked, prevented by a mechanical fitting, or disconnected from the gas supply and open pipe ends sealed?	Satisfactory
[192.603(b)][192.727(e)]	Did the operator maintain documentation when air was used for purging that a combustible mixture was not present after purging?	Satisfactory
[192.727(g)][192.727(g)]	Did the operator maintain documentation for each abandoned onshore pipeline facility that crosses over, under or through a commercially navigable waterway?	Not Applicable
General Comment:	<u>.</u>	
The Marion and Carbondale areas do not have pi	pelines that cross commercially navigable waterways.	
PRESSUI	RE LIMITING AND REGULATION	Status
Category Comment:		
Staff reviewed the pressure and regulation station	inspections on the Gas Compliance database for 2012 and 2013.	
[192.603(b)][192.739(a)]	Is the operator inspecting and testing the pressure limiting and regulating stations at a minimum of 1 per year/15 months?	Satisfactory
[192.603(b)][192.743(a)]	Is the operator inspecting pressure limiting and regulating stations for adequate capacity at a minimum of 1 per year/15 months?	Satisfactory
[192.603(b)][192.743(b)]	If the operator used calculations to determine sufficient capacity, were the calculation reviews documented at a minimum of 1 per year/15 months?	Satisfactory
[192.603(b)][192.741(a),192.741(b)]	Is each distribution system supplied by more than one district pressure regulating station, or where required by the operator on a system supplied by a single regulating	Not Checked

	station, equipped with telemetering or recording pressure	
	gauges to indicate the gas pressure in the district?	
General Comment:		
Each distribution system supplied by more than one or regulating station is equipped with a ERX and is sent	district pressure regulating station, or where required by the operator on a system sup to a different location with the SCADA system.	oplied by a single
[192.603(b)][192.741(c)]	If there were indications of abnormally high- or low- pressure, were actions taken to correct any unsatisfactory operating conditions?	Not Checked
General Comment:	•	
Each distribution system supplied by more than one or regulating station is equipped with a ERX and is sent	district pressure regulating station, or where required by the operator on a system sup to a different location with the SCADA system.	oplied by a single
[192.603(b)][192.743(a),192.743(b),192.19	95(b)(2)] Is overpressure protection provided by the supplier pipeline downstream of the take point?	Yes
[192.603(b)][192.743(a)]	If Yes, does the operator have documentation to verify that these devices have adequate capacity?	Satisfactory
VA	ALVE MAINTENANCE	Status
[192.603(b)][192.747(a),192.747(b)]	Did the operator inspect and maintain distribution valves necessary for the safe operation of the system at a minimum of 1 per year/15 months?	Satisfactory
General Comment:		
Staff reviewed the valve inspection records for 2012	and 2013.	
[192.603(b)][192.749(a)]	Did the operator inspect and maintain vaults > 200 cubic feet at a minimum of 1 per year/15 months?	Satisfactory
General Comment:	•	
Staff reviewed the inspection records on the Gas Con	mpliance Database for the single vault on College St for 2012 and 2013.	
Inv	restigation Of Failures	Status
[192.603(b)][192.617]	Did the operator experience accidents or failures requiring analysis?	Not Checked
General Comment:		
The records regarding failures are located at the Paw	rnee location.	
WE	LDING OF STEEL PIPE	Status
Category Comment:		
The welding qualification records are kept at the Paw	nee location.	
[192.603(b)][192.225(b)]	Does the operator have documentation for their qualified welding procedure?	Not Checked
	Does the operator have documentation of welder	

	qualification documentation as required?	
[192.709][192.243(b)(2)]	Does the operator have documentation of NDT personnel qualification as required?	Not Checked
[192.709][192.243(f)]	Does the operator have documentation of NDT testing performed?	Not Checked
JOINING O	F MATERIAL OTHER THAN WELDING	Status
Category Comment:		
The joining records are kept at the Pawnee loc	ation.	
[192.603(b)][192.285]	Are persons making joints with plastic pipe qualified?	Not Checked
[192.603(b)][192.287]	Are persons inspecting plastic pipe joints qualified?	Not Checked
[192.603(b)][192.283]	Are qualified joining procedures for plastic pipe in place?	Not Checked
COR	ROSION CONTROL RECORDS	Status
Category Comment:  Staff reviewed isolated test points and cathodic Atmospheric Corrosion Records for 2012 and 2	protection readings for the Carbondale and Marion locations in the Ameren GCS database 1013. Staff also reviewed rectifier inspections for Marion, Carbondale, Elizabethtown, and C	e. Staff reviewed Cave in Rock.
[192.491(a)][192.491(a)]	Has the operator maintained maps or records of cathodically protected piping, cathodic protection facilities, galvanic anodes, and neighboring structures bonded to the cathodic protection system?	Satisfactory
[192.491][192.459]	Has the operator maintained documentation of an examination when buried pipe was exposed?	Satisfactory
[192.491][192.465(a)]	Has the operator maintained documentation of annual pipe-to-soil monitoring performed at a minimum of 1 per yr/15 months and/or isolated services or short sections of main less than 100 feet at a minimum of 10% annually?	Satisfactory
[192.491][192.465(b)]	Has the operator maintained documentation of rectifier or other impressed current power sources inspections at a minimum of 6 per year/ 2 1/2 months?	Satisfactory
[192.491][192.465(c)]	Has the operator maintained documentation of each critical interference bond, reverse current switch, diode, etc. inspections at a minimum of 6 per year/ 2 1/2 months and/or non-critical interference bond inspections at a minimum of 1 per year/15 months?	Satisfactory
[192.491][192.465(d)]	Has the operator taken prompt remedial actions to correct any deficiencies indicated by the monitoring?	Satisfactory
General Comment:		
Staff reviewed atmospheric corrosion records for	or 2012 and 2013 in the Gas Compliance Database.	
[192.491][192.465(e)]	Has the operator maintained documentation of	Not Applicable

[520.10(a) (1)]	Has the operator maintained documentation demonstrating that personnel have received adequate training?	Not Checked
The training records are kept at the Pawnee location.	- I., .,	
Category Comment:		
TRAINING -	83 IL ADM. CODE 520	Status
[192.491][192.483(a),192.483(b),192.483(c)]	Has the operator maintained documentation demonstrating that pipe removed due to external corrosion has been repaired or replaced with pipe that was coated and cathodically protected?	Satisfactory
[192.491][192.479]	Has the operator maintained documentation of corrective action where atmospheric corrosion was discovered?	Satisfactory
[192.491][192.481]	Has the operator maintained documentation of atmospheric corrosion control monitoring at a minimum of 1 per 3 years/ 39 months?	Satisfactory
[192.491][192.477]	Has the operator maintained documentation of internal corrosion coupon monitoring at a minimum of 2 per year/ 7 1/2 months?	Not Applicable
[192.491][192.475(b)]	Has the operator maintained documentation of internal surface inspections performed when pipe is removed for any reason?	Not Applicable
[192.491][192.475(a)]	Has the operator maintained documentation of investigations or steps taken to minimize internal corrosion due to transportation of corrosive gas?	Not Applicable
[192.491][192.473(b)]	Has the operator maintained documentation of inspections or tests to assure their cathodic protection system is not affecting adjacent underground metallic structures?	Satisfactory
[192.491][192.471]	Has the operator maintained documentation of corrective actions taken when a test lead is no longer electrically conductive?	Satisfactory
[192.491][192.469]	Does the operator have a sufficient number of test stations or other contact points for electrical measurement to determine the adequacy of cathodic protection?	Satisfactory
[192.491][192.467(a),192.467(c),192.467(d)]	Has the operator maintained documentation of inspections or tests for electrical isolation at casings?	Satisfactory
Ameren does not have any unprotected pipelines in the Mari	on or Carbondale areas.	
General Comment:		
	unprotected pipeline surveys, inspections, or tests at a minimum of 3 years/39 months?	

Do training records include verbal instruction and/or on the job training for each job classification?	Not Checked
 Has the municipal operator maintained documentation demonstrating that personnel have received adequate training?	Not Checked
Are procedures periodically updated to include new materials, new methods of operation and installation, and changes in general procedures?	Not Checked